

Safe Filling of Cryogenic Liquid Dewars

Wear appropriate personal protective equipment




Only fill into a container intended for cryogen storage



Do **not** leave the area while filling



Close the valve and check the level to avoid overfilling.
Cryogen droplets can crack floor tiles.



**In case of a spill, alert the NIH Fire Department:
Dial 911 (or 301-496-9911 with a mobile phone)**

NIH Oxygen Monitoring Program Manager (non-emergency):
(301) 496-3353